



State of Oregon  
Department of  
Environmental  
Quality

# Underground Storage Tank Public Record

## General Program Information

### for Federal Fiscal Year 2024

Public record posted date: Oct 28, 2024

Oregon Department of Environmental Quality  
Underground Storage Tank Program  
700 NE Multnomah St., Suite #600  
Portland OR 97232  
Contact: Diana Foss  
[Diana.Foss@deq.oregon.gov](mailto:Diana.Foss@deq.oregon.gov)  
503-229-5733

---

## General Information

Total number of UST facilities: 1,779

Total number of USTs: 5,477\*

\* This number reflects all tanks that are believed to be federally regulated and have not been permanently closed.

## Summary Information for Inspections on Site

Number of UST facilities inspected: 259

Inspection period dates: 10/1/23 to 9/30/24

Percent compliance (combined measure): 38.61%

Note: Tank, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in Title 40 of the Code of Federal Regulations 280.12, except for those identified in 40 CFR 280.10(b) and 280.10(c) as excluded or deferred USTs. Inspection information provided above includes emergency generator USTs. On-site inspections are comprehensive compliance inspections measuring technical compliance rate as defined by the U.S. Environmental Protection Agency.

## Summary Information for Releases

Number of confirmed UST releases: 37

Release reporting period dates: 10/1/23 to 9/30/24

---

## Translation or other formats

[Español](#) | [한국어](#) | [繁體中文](#) | [Русский](#) | [Tiếng Việt](#) | [العربية](#)

800-452-4011 | TTY: 711 | [deqinfo@deq.oregon.gov](mailto:deqinfo@deq.oregon.gov)

**Summary Information for Release Sources and Causes** (totals may not equal 100% due to rounding)

Source			Causes													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	14	39%	0	0%	1	7%	0	0%	2	14%	0	0%	0	0%	10	71%
Piping	4	11%	0	0%	0	0%	2	50%	1	25%	0	%	0	%	1	25%
Dispenser	7	19%	0	0%	1	14%	0	0%	0	0%	0	0%	0	0%	6	86%
STP	1	7%	0	0%	0	0%	1	100%	0	0%	0	0%	0	0%	0	0%
Delivery Problem	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Other	6	16%	0	0%	0	0%	1	17%	0	0%	0	0%	0	0%	5	83%
Unknown	5	14%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	5	100%
<b>Totals</b>	<b>37</b>	<b>100%</b>	<b>0</b>	<b>0%</b>	<b>2</b>	<b>5%</b>	<b>4</b>	<b>12%</b>	<b>3</b>	<b>8%</b>	<b>0</b>	<b>0%</b>	<b>0</b>	<b>0%</b>	<b>27</b>	<b>73%</b>

# = number, % = percent of total number

Notes:

- (1) Release, source and cause information is based on USTs regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12.
- (2) Staff collected source and cause data at the time of reported release either by phone or on-line and verified by phone and entered it into the Leaking Underground Storage Tank Database. Project managers may update the data as additional information is available on the source and cause of the release.
- (3) Link to specific site projects- public portal in YDO [Oregon DEQ - Public Project Records](#)  
DEQ regional tank staff can provide additional site-specific compliance and release information.

**Translation or other formats**

[Español](#) | [한국어](#) | [繁體中文](#) | [Русский](#) | [Tiếng Việt](#) | [العربية](#)

800-452-4011 | TTY: 711 | [deqinfo@deq.oregon.gov](mailto:deqinfo@deq.oregon.gov)

- (4) For more details or to obtain a paper or electronic copy of this report, contact Diana Foss.

### **Non-discrimination statement**

DEQ does not discriminate on the basis of race, color, national origin, disability, age, sex, religion, sexual orientation, gender identity, or marital status in the administration of its programs and activities. Visit DEQ's [Civil Rights and Environmental Justice page](#).

---

### **Translation or other formats**

[Español](#) | [한국어](#) | [繁體中文](#) | [Русский](#) | [Tiếng Việt](#) | [العربية](#)

800-452-4011 | TTY: 711 | [deqinfo@deq.oregon.gov](mailto:deqinfo@deq.oregon.gov)